Work Orde May 18, 2010 7:		729										Page 1
Item ID: Revision ID:	D4034-041		1	Accept					Setup S	Start		
Item Name:	Aft Upper Rib	Assembly		•	•	· ·			S	Stop		
Start Date: Required Date: Reference:	5/18/10	Start Qty: 3.00 Req'd Qty: 3.00	Names on the		Cust Item I Customer:	D:						
Approvals:	Process Pla		Date: 10[5]]	Tooling: SPC (Y/N):	17/4-14/4	te:		4. X		Start		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty			Insp. Stamp
Draw Nbr	Rev	ision Nbr		10001.					4.			
D4034 100 Large Fab Large Fab	A	Memo 1- Assem	S.S. rod Batch: M///6/79 S.S. rod Batch: M///6/79 Subject to hoop and weld as perpending in rib and grind weld fl	0.00 r dwg DT9564	Ph 10.06.	04	·	3	þ) — — —		
QC Quality Control		QC9- Inspect visual p	er QS1004- Fusion Welds	0.00			(3 R	10,0	<u> </u>	. <u></u>	

QC5- Inspect part completeness to step on W/O

120 QC

Memo

0.00 S woloblo 3

Quality Control

Dart Aeros	pace	Ltd
------------	------	-----

W/O:	WORK ORDER CHANGES										
DATE	STEP	PRO	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		·							T Tou High		
				•							
				•							
Part No.		DAD #.	Fault Ca		NOD						
raitivo			Fault Category: N								
		esolution:		····					Date:	101/- St	
NCR:	· · · · · · · · · · · · · · · · · · ·		WORK OR	DER NON-CONFORMA	NCE	(NCH)					
DATE	STEP	Description of NC	Initial		Section B			ation	Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector	
									!	-	
									,		
								:			
:						÷					
	1									ŀ	

NOTE: Date & initial all entries

[▶] H:\fFO'RMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 58729

May 18, 2010 7:55:25 AM

Page 2

Item ID:

D4034-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Aft Upper Rib Assembly

Start Date:

5/18/10

Start Qty: 3.00

Req'd Qty: 3.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Required Date: 5/25/10

Process Plan: Date:

Date:

Tooling:

SPC (Y/N):

Date:

Draw

Rev.

Plan

Code

Date:

Run

Reject

Qty

Start

Stop



Number Stamp

Insp.

Sequence ID/ **Work Center ID**

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location: WA

Set Up/ Run Hours

0.00 SAO

10-08-67

Accept

Qty

Reject

140

Quality Control

OC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

0.00

10/06/07 Hy

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			SES	; <u>-</u>							
DATE	STEP	PRO	PROCEDURE CHANGE						Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		,									
									:		
Part No	:	PAR #:	Fault Cate	gory:	_ NCF	R: Yes	No DQ	\ \:	Date:		
			Disposition:								
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Secondarial Action Description			Sign &	Verification		Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng		Date			Chief Eng	QC Inspector	
										-	
	-					•					
					1						

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print

May 18, 2010 7:55:25 AM

Work Order ID: 58729

_ . .

D4034-041

Parent Item Name:

Aft Upper Rib Assembly

Comments:

Parent Item:

IPP RevA: new issue DD 09.11.23 verified by:EC

per dwg revA 10.03.15 verified by:EC



IPP Rev:B as

Start Date: 5/18/10

Required Date: 5/25/10

Start Qty: 3.00

Required Qty: 3.00

	Replacement Item ID	Mfg/ Purch Manufactured	Bin Item No	Primary Location	Last Location	Route Seq ID 100	Unit of Measure Each	Qty on Hand 6.0000	Qty per Kit	Qty Issued # N ~	Date Issued	Status
				<u>Locatio</u> WA	on B 58693 = 200003	Loc	Oty 6 6	Loc Code	_	.3		
D4034-3	H	Manufactured	No		B58695 =	100 = 3	Each	0.0000		01	·06 ·04)
D4021-7		Manufactured	No	-		100	Each	5.0000	1	St 10	.06.04	,
,				<u>Locatio</u> WA	n B58702 58039 58484	Loc	Oty 5 1 4	Loc Code	- -	3		
D4021-9		Manufactured	No	•	30101	100	Each	16.0000	2	PER	06.04	
-				<u>Locatio</u> WA	56094 58404	<u>Loc</u>	Otv 16 2 14	Loc Code	-			

Page 1

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:		,	ES							
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							ļ			
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _		
					QA: N/C Closed: Date:					
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	R)				
DATE	STEP	Description of NC		on B	Verific	Verification A		Approval		
	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti		Approval Chief Eng	QC Inspector	
									-	

NOTE: Date & initial all entries

H:\fFÓRMS\Quality Assurance\approved QA\NCRWO RevE







